K

Page 1 of 1

Suzanne Steab - June 2010 Inspection Report

From:

Karl Houskeeper

To:

GGalecki@archcoal.com

Date:

7/8/2010 9:09 AM

Subject:

June 2010 Inspection Report

CC:

 $ANGELANANCE @utah.gov; \\ DARONHADDOCK @utah.gov; \\ SUZANNESTEAB @utah.gov$

Attachments: Skyline June 2010.pdf

Gregg,

Attached is the June 2010 inspection report for Skyline.

Thanks,

Karl



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:						
Company	Gregg Galecki Environmental Coordinator					
OGM	Karl Houskeeper Environmental Scientist III					

Inspection Report

Permit Number:	C0070005
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, June 23, 2010
Start Date/Time:	6/23/2010 7:30:00 AM
End Date/Time:	6/23/2010 11:30:00 AM
Last Inspection:	Wednesday, May 05, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 49 Deg. F. InspectionID Report Number: 2404

> Accepted by: jhelfric 6/24/2010

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SKYLINE MINE

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current	Acreages
---------	-----------------

	Total Permitted	
84.25	Total Disturbed	
	Phase I	
	Phase II	
	Phase III	

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground ✓ State ☐ Surface ☐ County ☐ Loadout **✓** Fee ☐ Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper, Environmental Scientist III

Date

Wednesday, June 23, 2010

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Where ideas connect

Permit Number: C0070005

Inspection Type: PARTIAL

Inspection Date: Wednesday, June 23, 2010

Inspection Continuation Sheet

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
- a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not a. For COMPLETE inspections provide narrative justification for any elements not fully inspected anness standard appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
 4. Provide a brief status report for all pending enforcement actions, permit conditions. Divison Orders, and amendments.

- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		V	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	V		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	V			
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.					
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070005

Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Wednesday, June 23, 2010

Page 3 of 3

2. Signs and Markers

Mine identification signs are located at points of public access to the permit area. The signs contain the required information.

4.a Hydrologic Balance: Diversions

Large rock in diversion by truck load out and coal storage pile. Rock needs to be removed from the diversion.